

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, February 10, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13690+91 – 13748+30 ATWS 562/1362	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: W-EF4, S-E28, W-E7, W-E8, S-E28 and S-EF4.

- STA 13693+08: Bank scour at S-E28 crossing from high flow conditions. Bank stabilization needed.
- STA 13704+90: Bank scour at S-E28 crossing from high flow conditions. Bank stabilization needed.

Recommended Corrective Action: Stabilize bank scour.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Monday, February 10, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, February 10, 2020

Figure 1: STA 13693+08 – Bank scour along S-E28 crossing from high flow conditions. Bank stabilization needed.



Figure 2: STA 13704+90 – Bank scour along S-E28 crossing from high flow conditions. Bank stabilization needed.



Figure 3: STA 13721+00 – Controls in place and functioning properly.



Figure 4: Stream S-EF4 – Controls in place and functioning properly at stream S-EF4.

