

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, February 4, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13562+38 – 13644+82 MVP-FR-323 ATWS 1416/1417/1067	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: W-GH2, S-GH6, S-II6 and S-E28.

Ineffective Controls: (24-Hour Deadline from Notification)

- STA 13574+25: End-treatment maintenance needed. CFS undermined.
- STA 13630+00: Permanent end-treatment maintenance needed. Level spreader undermined.
- STA 13629+50: CFS maintenance needed. CFS undermined.
- STA 13629+45: Permanent end-treatment maintenance needed. Level spreader undermined.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, February 4, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, February 4, 2020

Figure 1: STA 13574+25 – CFS end-treatment undermined. Maintenance needed.



Figure 2: STA 13630+00 – Permanent end-treatment level spreader undermined. Repair needed.



Figure 3: STA 13629+50 – CFS undermined. Maintenance needed.



Figure 4: STA 13629+45 – Permanent end-treatment level spreader undermined. Repair needed.

