

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, January 29, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13316+13 – 13415+51 ATWS 1352	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-IJ3, W-IJ2-PSS, S-IJ2, W-IJ1, S-IJ1, S-RR11, S-RR09, S-RR08, S-GH9, S-GH11, S-GH14 and S-GH15.

Ineffective Controls: (24-Hour Deadline from Notification)


- STA 13411+00: End-treatment maintenance required. End treatment undermined.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, January 29, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, January 29, 2020

Figure 1: STA 13413+00 – Controls in place and functioning properly around Stream S-IJ1.



Figure 2: STA 13411+00 – End treatment CFS undermined. Maintenance needed.



Figure 3: STA 13371+00 – Controls in place and functioning properly. Area stabilized with erosion matting.



Figure 4: STA 13333+00 – Controls in place and functioning properly above Stream S-GH11.

