

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, January 28, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15647+03 – 15743+08 MVP-PI-336.01/337 ATWS 1392/497/498/625/626/627	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-Q4, W-Q2, S-Q3, S-Q2, W-Q1, S-B7, S-B8 and S-KL20.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 15656+00: CFS undermined. Maintenance needed.

Ineffective Controls: (24-Hour Deadline from Notification)

- ATWS 498: End-treatment maintenance needed. CFS undermined.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Various - See Comments

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, January 28, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, January 28, 2020

Figure 1: STA 15656+00 – CFS undermined. Maintenance needed.



Figure 2: Wetland W-Q2 – Controls in place and functioning properly.



Figure 3: ATWS 498 – End treatment CFS undermined. Maintenance needed.



Figure 4: Stream S-B6 – Controls in place and functioning properly.

