

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, January 27, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13333+96 – 13337+82	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-GH9 and S-GH11.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Monday, January 27, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, January 27, 2020

Figure 1: Stream S-GH11 – Controls in place and functioning properly. Area stabilized with erosion matting and vegetation. No evidence of sediment discharge off ROW.

☼ 310°NW (T) ● 37°6'16"N, 80°2'46"W ±16.4ft ▲ 1459ft



Figure 2: Stream S-GH11 – Looking upstream of ROW at S-GH11 crossing.

☼ 40°NE (T) ● 37°6'16"N, 80°2'46"W ±16.4ft ▲ 1459ft



Figure 3: Stream S-GH9 – Controls in place and functioning properly. Area stabilized with erosion matting. No evidence of sediment discharge off ROW.

☼ 323°NW (T) ● 37°6'15"N, 80°2'42"W ±16.4ft ▲ 1466ft



Figure 4: Stream S-GH9 – Controls in place and functioning properly. Area stabilized with erosion matting. No evidence of sediment discharge off ROW.

☼ 148°SE (T) ● 37°6'15"N, 80°2'43"W ±32.8ft ▲ 1457ft

