

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, March 3, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15584+23 - 15647+03 ATWS 813/1445	Weather:	Rainy

Pitt	sylvania County	ATWS 813/1445		weather.		Kalliy							
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling	Felling Clearing/Grubbing Grade		ding	nching		Strin	nging/Weldin					
	Lowering/Backfilling	g/Backfilling \square Final Restoration \square Temp. Stabilization \square Perm. Stabilizatio				m. Stabilization	n 🗵 Dormant						
						,	Yes	No	N/A				
	 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? 												
	3. Areas of	offsite sediment deposition of	bserved?		·			\boxtimes					
	<u>Comments:</u> Inspected the following resources: W-MM9, S-CC1, W-MM8-PEM, W-MM8-PFO, S-CC3, S-P5 and S-IJ35-EPH. Recommended Corrective Action: N/A												
	<u>Deadline:</u> N	<u>/A</u>											
	The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.												
	Inspector Sig	nature: MMMul	l Win	<u>lid</u>									
	Date Tues	day March 3 2020											



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

<u>Date</u>: Tuesday, March 3, 2020

Figure 1: **STA 15589+00** – Controls in place and functioning properly.



<u>Figure 2</u>: **Stream S-CC1** – Controls in place and functioning properly.



<u>Figure 3</u>: **Stream S-IJ35-EPH** – Controls in place and functioning properly.



Figure 4: STA 15641+00 – Controls in place and functioning properly. Area stabilized with Earth-Guard.

