

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, June 2, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12072+50 – 12188+34 MVP-MN-270/271/273/274 ATWS 1163/1162/701/1167/1168	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-MM15, S-MM14, S-MM13, S-MM11, S-F15, W-F9-PFO, W-C12, S-C33, S-C36, W-C11, S-MM31, S-C29, W-C6, W-C5, S-C25 and S-C24.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Tuesday, June 2, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, June 2, 2020

Figure 1: STA 12072+00 – Controls in place and functioning properly. Area stabilized.

☼ 332°NW (T) ● 37°13'57"N, 80°15'41"W ±6391ft ▲ 1349ft



Figure 2: STA 12085+00 – Controls in place and functioning properly. Area stabilized.

☼ 108°E (T) ● 37°14'10"N, 80°15'43"W ±6391ft ▲ 1765ft



Figure 3: STA 12120+00 – Controls in place and functioning properly. Area stabilized.

☼ 97°E (T) ● 37°14'8"N, 80°15'40"W ±6391ft ▲ 1493ft



Figure 4: STA 12155+00 – Controls in place and functioning properly. Area stabilized.

☼ 55°NE (T) ● 37°14'7"N, 80°15'40"W ±6391ft ▲ 1437ft

