

## FIELD INSPECTION REPORT

|                                      |                                                                      |                         |                             |
|--------------------------------------|----------------------------------------------------------------------|-------------------------|-----------------------------|
| <b>Project Name:</b>                 | Mountain Valley Pipeline                                             | <b>Inspector:</b>       | Marshall Willis             |
| <b>Inspection Date:</b>              | Wednesday, May 27, 2020                                              | <b>Project Contact:</b> | Brian Clauto, Cory Chalmers |
| <b>Spread H:<br/>Franklin County</b> | STA 13306+16 – 13316+00<br>STA 13411+83 – 13415+51<br>ATWS 1412/1352 | <b>Weather:</b>         | Rainy                       |

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- |                                               |                                            |                                              |                                              |                                             |
|-----------------------------------------------|--------------------------------------------|----------------------------------------------|----------------------------------------------|---------------------------------------------|
| <input type="checkbox"/> Tree Felling         | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading             | <input type="checkbox"/> Trenching           | <input type="checkbox"/> Stringing/Welding  |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- |                                                                                                                                                                                    | Yes                                 | No                                  | N/A                      |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?                                                                                                                                  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-GH7, S-IJ3, W-IJ2-PSS, W-IJ1, S-IJ2 and S-IJ1.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Wednesday, May 27, 2020

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, May 27, 2020

**Figure 1: STA 11306+50** – Controls in place and functioning properly at the Wades Gap crossing.

☉ 124°SE (T) ☉ 37°6'23"N, 80°3'6"W ±328ft ▲ 1310ft



**Figure 2: Stream S-GH7** – Controls in place and functioning properly around S-GH7 crossing. Area stabilized.

☉ 283°W (T) ☉ 37°4'30"N, 80°3'14"W ±14098ft ▲ 1426ft



**Figure 3: STA 11306+50** – Controls in place and functioning properly at the Cahas Road crossing.

☉ 317°NW (T) ☉ 37°5'34"N, 80°1'31"W ±16ft ▲ 1492ft



**Figure 4: Stream S-IJ1** – Controls in place and functioning properly at stream S-IJ1 crossing. Area stabilized.

☉ 296°NW (T) ☉ 37°5'34"N, 80°1'39"W ±16ft ▲ 1456ft

