

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, May 19, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12183+00 – 12203+00 STA 12117+00 – 12120+00 MVP-MN-274/275 ATWS 703/1446/1062/704/1375	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-C21 and S-OO11.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Tuesday, May 19, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, May 19, 2020

Figure 1: STA 12187+00 – Controls in place and functioning properly.

☼ 301°NW (T) ● 37°15'8"N, 80°15'36"W ±16ft ▲ 1290ft



Figure 2: Stream S-C21 – Controls in place and functioning properly around Bradshaw Creek crossing.

☼ 37°NE (T) ● 37°15'5"N, 80°15'33"W ±32ft ▲ 1269ft



Figure 3: STA 12200+00 – Controls in place and functioning properly.

☼ 59°NE (T) ● 37°15'4"N, 80°15'24"W ±2788ft ▲ 1286ft



Figure 4: STA 12118+00 – Controls in place and functioning properly.

☼ 354°N (T) ● 37°15'26"N, 80°16'57"W ±32ft ▲ 1405ft

