

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, May 12, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12298+39 – 12371+10 ATWS 1374 MVP-MN-276.03	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: N/A.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Tuesday, May 12, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, May 12, 2020

Figure 1: MVP-MN-276.03 – Controls in place and functioning properly along MVP-MN-276.03. Area stabilized with erosion control matting.

☉ 146°SE (T) ☉ 37°15'24"N, 80°13'36"W ±16ft ▲ 2659ft



Figure 2: STA 12300+00 – Controls in place and functioning properly. Area stabilized with erosion control matting.

☉ 134°SE (T) ☉ 37°15'16"N, 80°12'55"W ±3025ft ▲ 2601ft



Figure 3: STA 12334+00 – Controls in place and functioning properly. Area stabilized with erosion control matting.

☉ 77°E (T) ☉ 37°15'9"N, 80°12'55"W ±16ft ▲ 1726ft



Figure 4: STA 12363+00 – Controls in place and functioning properly. Area stabilized with erosion control matting.

☉ 3°N (T) ☉ 37°14'41"N, 80°12'43"W ±15906ft ▲ 1429ft

