

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, December 31, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13197+55 – 13316+13 MVP-FR-293.01	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-GH7 and S-II4.

Recommended Corrective Action: N/A.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 12/31/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, December 31, 2019

Fig. 1: **STA 13306+00** – Controls in place and properly functioning. Area stabilized.

☼ 355°N (T) ● 37°6'24"N, 80°3'18"W ±98.4ft ▲ 1378ft



Fig. 2: **STA 13273+00** – Controls in place and properly functioning. Area stabilized.

☼ 282°W (T) ● 37°6'55"N, 80°3'23"W ±32.8ft ▲ 1634ft



Fig. 3: **STA 13254+00** – Controls in place and properly functioning. Area stabilized.

☼ 101°E (T) ● 37°6'56"N, 80°3'43"W ±32.8ft ▲ 1620ft



Fig. 4: **STA 13230+00** – Controls in place and properly functioning. Area stabilized.

☼ 151°SE (T) ● 37°7'21"N, 80°4'1"W ±98.4ft ▲ 2046ft

