

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, December 30, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13415+51 – 13541+66 MVP-FR-293.02/294	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Dormant

- | | Yes | No | N/A |
|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-IJ4, S-IJ8, W-IJ6, S-IJ10, S-KL2, W-EF43, S-II8, S-II7, and W-II8.

- STA 13464+00: P1 maintenance needed.
- STA 13467+50: CFS maintenance needed.
- STA 13472+00: P1/CFS maintenance needed.
- STA 13485+50: Waterbar maintenance needed.
- STA 13486+00: Waterbar maintenance needed.
- STA 13506+00: P1 maintenance needed.

Recommended Corrective Action: Maintain and install all controls per the approved plans and PSS&S.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 12/30/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, December 30, 2019

Fig. 1: **STA 13464+00** – P1 maintenance needed.



Fig. 2: **STA 13467+50** – CFS maintenance needed.



Fig. 3: **STA 13472+00** – P1 and CFS maintenance needed.



Fig. 4: **STA 13485+50** – Waterbar maintenance needed.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, December 30, 2019

Fig. 5: **STA 13486+00** – Waterbar maintenance needed.



Fig. 6: **STA 13506+00** – P1 maintenance needed.

