

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, December 12, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County Franklin County	STA 15113+00 – 15142+66 STA 13853+45 – 13876+00 MVP-FR-303.01	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant


- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-H11, S-A6, S-C17, W-CD6 and S-CD6.

Recommended Corrective Action: N/A

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: 12/12/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, December 12, 2019

Fig. 1: **Stream S-H11** – Controls in place and properly functioning. Area stabilized with Earth Guard.



Fig. 2: **Stream S-A6** – Controls in place and properly functioning. Area stabilized with Earth Guard.



Fig. 3: **STA 13860+00** – Controls in place and functioning above Stream S-C17. Area stabilized with vegetation.



Fig. 4: **STA 13867+57** – Controls in place and properly functioning. Area stabilized with vegetation.

