

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, November 21, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12102+69 – 12203+82 MVP-MN-271/270.01/274 ATWS 703/704/704A/1375	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-C21, S-OO11, S-F16a/b, S-F15, W-F9-FRO, S-C36, W-C11, W-C12, S-C33, S-MM31, S-C29, W-C6, W-C5, S-C25, S-MM11 and S-NN16.

Recommended Corrective Action: N/A

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 11/21/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, November 21, 2019

Fig. 1: **STA 12102+77** – Controls in place and functioning. Area stabilized.



Fig. 2: **STA 12115+00** – Controls in place. Area stabilized with straw and erosion control matting.



Fig. 3: **STA 12190+85** – Controls in place along Bradshaw Road. Controls functioning at the time of inspection.



Fig. 4: **S-C21** – Controls in place and functioning along Bradshaw Creek.

