

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, November 21, 2019	Project Contact:	Brian Clauto
Spread: Montgomery Co. MP 229-231 AR 270.01 ATWS1062 ATWS 10446 ATWS 704A	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments:

- Inspected designated streams and wetlands included: S-MM11, S-F15, W-F9PFC, S-F16AB, S-C33, S-C36, W-C11, W-C12, S-MM31, S-C29, W-C5, S-C25, S-C21, S-0011
- ECD's were in place and functioning at the designated crossings.

Recommend Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.


Inspector Signature: Matthew Grant Date: 12-2-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, November 21, 2019

- Fig. 1. Above designated stream S-MM11, ECD's in place and functioning.



- Fig. 2. Near MP 230.6 area has been stabilized with straw and propanics.



- Fig. 3. At designated stream S-C21, ECD's are in place and functioning.



- Fig. 4. Near MP 230.8 ECD's are in place and functioning.

