

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, December 4, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County Roanoke County	STA 12545+19 – 12544+06 MVP-MN-278.01/RO-270.01 MVP-MLV-AR-28	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-CD12b, W-KL58 and S-EF19.

PPL actively performing routine maintenance in the approx. areas: STA 12482+00 to STA 12532+00.

Recommended Corrective Action: N/A

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 12/04/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, December 4, 2019

Fig. 1: **STA 12536+50** – Controls in place and functioning properly.



Fig. 2: **STA 12518+50** – Controls in place along Stream S-EF19.



Fig. 3: **STA 12502+00** – Controls in place and functioning properly.



Fig. 4: **STA 12471+00** – Controls in place and functioning properly.

