

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, December 4, 2019	Project Contact:	Brian Clauto
Spread: Montgomery Co. AR MN 278.01 ATWS 645 ATWS 1225 ATWS 1224 Roanoke Co. MP240.2-240 MP239.2 AR-RO 279.01	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments:

- Inspected designated streams and wetlands included: S-EF19, W-CD11, W-CD11UP
- ECD's were in place and functioning at the designated crossings.
- During the inspection ECD maintenance was being conducted.

Recommend Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 12-16-19

FIELD INSPECTION PHOTO LOG


Project Name: Mountain Valley Pipeline

Date: Wednesday, December 4, 2019

- Fig. 1. Near MP 237.5 stockpiles have been stabilized.



- Fig. 2. Near MP 237.2 slope drains are functioning and ECD maintenance is being conducted.



- Fig. 3. Near MP 237.3 ECD maintenance was being conducted.



- Fig. 4. Above designated stream S-EF19, ECD's are in place and functioning.

