

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis	
Inspection Date:	Friday, October 25, 2019	Project Contact:	Brian Clauto, Cory Chalmers	
Spread I: Franklin County	STA 13575+21 - 13690+91	Weather (Wet/Dry/Rain):	Wet	

STAGE OF CONSTRUCTION: (Check all that apply)									
	Clearing Rough Grading Trench Excavation					Pipe Assembly, Testing & Installation			
☐ Backfilling and Grade Restoration ☐ Final Grading & Stabilization				\boxtimes	Other: Dormant				
		Yes	No	N/A					
1	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								
2	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?		\boxtimes						
3	Areas of offsite sediment deposition were observed?								
Comments: Inspected the following resources: S-E28, S-E29, W-II7, S-GH3, S-GH2 and S-II6. STA 13630+00: Maintain/repair CFS. STA 13631+00: Maintain/repair CFS.									
	STA 13631+50: Maintain/repair CFS. STA 13631+75: Maintain/repair CFS.								
Recommended Corrective Action: Maintain and install all controls per the approved plans and PSS&S.									

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Manual Million

Date: 10/25/2019



FIELD INSPECTION PHOTO LOG

<u>Project Name</u>: Mountain Valley Pipeline <u>Date</u>: Friday, October 25, 2019

Fig. 1: **STA 13630+00** – CFS undermined. Fig. 2: **STA 13631+00** – CFS undermined. Fig. 3: **STA 13631+50** – CFS undermined. Fig. 4: **STA 13631+75** – CFS maintenance needed. @ 217°SW (T) @ 37°5'25"N, 79°57'54"W ±16.4ft ▲ 1264ft ₱ 54°NE (T) ● 37°5'25"N, 79°57'54"W ±98.4ft ▲ 1266ft