

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, October 9, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13342+67 – 13415+51	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration
 ☒ Final Grading & Stabilization
 ☐ Other:

- | | Yes | No | N/A |
|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-IJ1, S-IJ2, W-IJ1, S-IJ3, W-IJ2, S-RR11, S-RR09 and S-RR08.

Recommended Corrective Action: N/A.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 10/09/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, October 9, 2019

Fig. 1: **Stream S-IJ1**– Controls in place and functioning properly at stream and wetland crossing.



Fig. 2: **STA 13395+00** – Controls in place. Area actively being graded back to subgrade.



Fig. 3: **STA 13370+00** – Controls in place. Area actively being graded back to subgrade.



Fig. 4: **Stream S-RR08** – Controls in place at stream crossing and functioning properly.

