

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, October 8, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12101+57 – 12200+00	Weather (Wet/Dry/Rain):	Rainy

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration
 ☒ Final Grading & Stabilization
 ☒ Other: Winterization/Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-OO11, S-C21, S-C24, S-C25, S-C29, S-MM31, S-C36, S-F15 and S-MM11.

Recommended Corrective Action: N/A.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 10/08/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, October 8, 2019

Fig. 1: **STA 12190+00** – Controls in place in place at Bradshaw Road.

☉ 71°E (T) ☉ 37°15'6"N, 80°15'35"W ±16.4ft ▲ 1307ft



Fig. 2: **STA 12200+00** – Controls in place. Area stabilized with hydraulic mulch and straw.

☉ 65°NE (T) ☉ 37°15'8"N, 80°15'24"W ±16.4ft ▲ 1307ft



Fig. 3: **STA 12117+62** – Controls in place. Area stabilized with straw and erosion matting.

☉ 288°W (T) ☉ 37°15'27"N, 80°16'58"W ±16.4ft ▲ 1446ft



Fig. 4: **Stream S-MM11** – Controls in place. Area stabilized with straw and erosion matting.

☉ 266°W (T) ☉ 37°15'30"N, 80°17'15"W ±16.4ft ▲ 1504ft

