

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, September 4, 2019	Project Contact:	Brian Clauto
Spread: Roanoke Co. MP240 12690+29-12712 ATWS1224 & 1225 ARO 280 AR 279.01 Montgomery Co. ATWS 1159 MP227.7-229.2 ST12031+56- 12103+00	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☒ Pipe Assembly, Testing & Installation

☒ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments:

- Inspected designated streams included: SG-36, SG-39, SG-40, S-MM15, S-MM14, S-MM13, S-MM11
- ECD's were in place for active construction and functioning at designated stream crossings.
- MP227.7-MP228.3 is dormant and stabilized

Recommend Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 10-9-19

FIELD INSPECTION PHOTO LOG


Project Name: Mountain Valley Pipeline

Date: Wednesday, September 4, 2019


- Fig. 1 Near MP 229 backfilling of trench



- Fig. 2 Near MP 228.3 area remains matted.



- Fig. 3 Near MP 240.3 waterbars have been matted



- Fig. 4 ECD's in place at AR279.01

