

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, December 19, 2018	Project Contact:	Brian Clauto
Spread: Montgomery County MP 227-228	Spread H	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☒ Pipe Assembly, Testing & Installation
- ☒ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☐ Other:

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |


Comments:

- Streams inspected included S-G 39, S-G 40. SP 23, MN15 and S-G36, all associated ESC were in place and functioning.

Recommended Corrective Action: n/a

Deadline: n/a

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 1/3/19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, December 19, 2018

- Fig. 1 St#12038+00 plunge pool installed and functioning.



- Fig. 2 designated stream crossing S-G36 controls in place and functioning.



- Fig. 3 St#10273+65 matting has been installed and is functioning.



- Fig. 4 St#12031+56 at designated stream S-G 39 controls in place and functioning.

