

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Monday, November 26, 2018	Project Contact:	Brian Clauto
Spread: Roanoke County MP243 St#12867-12865	Spread H	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Bore pit

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |


Comments:

- St#12867+08 – St#12865+11 all work being conducted was within the LOD, no construction was being conducted within the designated wetlands. Torn silt fence was observed at St#12865+11

Recommended Corrective Action: replace and maintain all controls per the annual standard and specs.

Deadline: Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 12-11-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, November 26, 2018

Fig. 1
Torn silt fence at St#12865+11



Fig. 2 Dewatering structure in place and functioning at the Bottoms Creek bore pit.



Fig. 3 Work within the LOD of the Bottoms Creek bore pit.



Fig. 4 Wetland perimeter at St#12867+64

