

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, September 26, 2018	Project Contact:	Brian Clauto
Spread: Montgomery County	Spread H	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☒ Trench Excavation
 ☒ Pipe Assembly, Testing & Installation
☒ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Stream crossing

- | | | Yes | No | N/A |
|---|---|-------------------------------------|--------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☒ | ☐ | ☐ |

Comments:

- **Area 1** – Follow up to inspection on 9/25/18, MP 227.9 station#12035+19 designated stream SG-40 additional controls below dewatering structure were installed, pump around rock outfall energy dissipater was installed. Remove sediment per DEQ approval.

Deadline: within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 11-5-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, September 26, 2018

Fig. 1
MP 227.9 St#12035+19 designated stream SG-40
dewatering structure outfall area



Fig. 2
MP 227.9 St#12035+19 designated stream SG-40 dewatering
structure outfall area



Fig. 3
Designated stream SG-40 pump around energy dissipater



Fig.4
Sediment in stream

