

COMPLAINT INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, April 23, 2019	Project Contact:	Brian Clauto
Spread G: Montgomery County	STA 11929+47 – 11988+96	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Dormant

- | | Yes | No | N/A |
|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: ROW inspected in Montgomery County from STA 11929+47 through STA 11988+96 in response to a complaint by a property owner of sediment laden water flowing off of the ROW and sediment entering a spring. Area of ROW inspected had ECDs in place and vegetative stabilization. Several minor rill erosion issues were discovered:

STA 11940+00: Repair rill erosion, stabilize slope.

STA 11948+00: Repair rill erosion, stabilize slope.

Recommended Corrective Action: Stabilize areas exhibiting erosion.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 04/23/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, April 23, 2019

Fig. 1: **STA 11930+00** – Area stabilized. Controls in place.



Fig. 2: **STA 11943+00** – Area stabilized. Controls in place.



Fig. 3: **STA 11938+35** – Area stabilized. Controls in place.



Fig. 4: **STA 11940+00** – Rill erosion occurring.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, April 23, 2019

Fig. 5: **STA 11943+00** – Area stabilized. Controls in place above karst feature.



Fig. 6: **STA 11948+00** – Rill erosion occurring.



Fig. 7: **STA 11969+00** – Area stabilized. Controls in place.



Fig. 8: **STA 11979+00** – Area stabilized. Controls in place.

