

## FIELD INSPECTION

|                              |                                      |                         |                             |
|------------------------------|--------------------------------------|-------------------------|-----------------------------|
| Project Name:                | Mountain Valley Pipeline             | Inspector:              | Marshall Willis             |
| Inspection Date:             | Monday, August 19, 2019              | Project Contact:        | Brian Clauto, Cory Chalmers |
| Spread I:<br>Franklin County | STA 14018+47- 14042+25<br>MVP-MLV-31 | Weather (Wet/Dry/Rain): | Dry                         |

**STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation  
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Dormant

- |                                                                                                                                                                                   | Yes                                 | No                                  | N/A                      |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2 Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 Areas of offsite sediment deposition were observed?                                                                                                                             | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |

Comments: Inspected the following resources: S- KL39

STA 14019+91: Stabilize slopes and area surrounding MLV-31.  
 STA 14033+50 to 14034+50: Waterbar maintenance required.  
 STA 14034+50: Sediment off ROW.

**Recommended Corrective Action:** Maintain and install all controls per the approved plan and PSS&S.

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 08/19/2019

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Monday, August 19, 2019

Fig. 1: **STA 14019+91** – Stabilize slopes and area adjacent to MLV-31.



Fig. 2: **STA 14033+50 to 14034+50** – Maintain waterbars.




Fig. 3: **STA 14033+50 to 14034+50** – Maintain waterbars.



Fig. 4: **STA 14034+50** – Sediment off ROW.

