

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, August 7, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County Montgomery County	STA 12445+19 – 12544+06 STA 12071+80 – 12102+69	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☒ Pipe Assembly, Testing & Installation

☒ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☐ Other:

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-EF19, S-MM15, S-MM14, and S-MM13.

STA 12082+28: Maintain sump.
 STA 12083+00: Maintain sump.
 STA 12093+28: Maintain sump.

Recommended Corrective Action: Install and maintain all controls per the approved plans and PSS&S.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 08/07/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, August 7, 2019

Fig. 1: **STA 12082+28** – Sump maintenance needed.



Fig. 2: **STA 12083+00** – Sump maintenance needed.



Fig. 3: **STA 12093+00** – Sump maintenance needed.



Fig. 4: **Stream S-MM13** – Perimeter controls in place. Bridge clean and sideboards in place and functioning.

