

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, August 6, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County Franklin County	STA 12656+89 – 12690+43 STA 13061+44 – 13083+96 STA 13260+75 – 13262+66 STA 13316+13 – 13306+16	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☒ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Conventional Bore

- | | | Yes | No | N/A |
|---|---|-------------------------------------|--------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☒ | ☐ | ☐ |

Comments: Inspected the following resources: S-IJ50, S-G26, S-G27, S-II4, and S-GH7.

Sediment retrieval from offsite discharge ongoing at Stream S-IJ50 (STA 12656+89).
 Conventional bore at Stream S-G26/G27 (STA 13061+89) is complete.
 Conventional bore at Stream S-II4 (STA 13260+75) is complete but tie-in ongoing.
 Conventional bore at Stream S-GH7 (STA 13309+09) is ongoing.

Recommended Corrective Action: N/A

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 08/06/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, August 6, 2019

Fig. 1: **STA 12690+43** – Off ROW impacts to Stream S-IJ50. Ongoing cleanup efforts underway.



Fig. 2: **Stream S-G26/27** – Conventional bore completed. Perimeter controls in place. Buffers stabilized. Bridge clean and sideboards installed and functioning properly.



Fig. 3: **Stream S-II4** – Conventional bore completed. Tie-in ongoing. Controls in place.



Fig. 4: **Stream S-GH7** – Conventional bore ongoing. Secondary containment and controls in place. Dewatering structures utilized and functioning at the time of inspection.

