

## **FIELD INSPECTION**

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, July 31, 2019	Project Contact:	Brian Clauto
Spread H: Montgomery County	STA 12445+19 - 12482+67 MVP-MLV-AR-28	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)					
☐ Clearing ☐ Rough Grading ☐ Trench Exce	Pipe Assembly, Testing & Installation				
☐ Backfilling and Grade Restoration ☐ Final Grading & Stabilizat	Other:				
	Yes No N/A				
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?					
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?					
3 Areas of offsite sediment deposition were observed?					
Comments: Inspected the following resources: S-CD12b and W-KL58.					
STA 12479+75 to 12480+00: SSF undermined.	STA 12479±75 to 12480±00: SSF undermined				
STA 12480+00: SSF cleanout required.					
STA 12480+00: Replace damaged bridge wattle.					
STA 12481+00: Replace damaged bridge wattle.					
STA 12482+00: SSF undermined.					
STA 12482+00: CFS maintenance required.					
STA 12483+00: Sump maintenance required. STA 12483+00: Waterbar failure.					
STA 12483+00. Waterbar failure. STA 12482+95: No end-treatment at end of waterbar, sump maintenance needed.					
on 12 102 100. No one treatment at one of waterbar, bump maintenance necess.					
Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.					

#### **Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Date: <u>07/31/2019</u>



### FIELD INSPECTION PHOTO LOG

<u>Project Name</u>: Mountain Valley Pipeline <u>Date</u>: Wednesday, July 31, 2019

Fig. 1: **STA 12479+75 to 12480+00** – SSF undermined. Fig. 2: STA 12480+00 - SSF maintenance required. Fig. 3: **STA 12480+00** – Replace damaged bridge wattle. Fig. 4: **STA 12481+00** – Replace damaged bridge wattle. 



### FIELD INSPECTION PHOTO LOG

<u>Project Name</u>: Mountain Valley Pipeline <u>Date</u>: Wednesday, July 31, 2019

Fig. 5: **STA 12482+00** – SSF undermined. Fig. 6: **STA 12482+00** – CFS maintenance needed. Fig. 7: **STA 12483+00** – Sump maintenance needed. Fig. 8: STA 12483+00 - Waterbar repair needed. 



# FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline <u>Date</u>: Wednesday, July 31, 2019

