

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, July 30, 2019	Project Contact:	Brian Clauto
Spread H: Montgomery County	STA 12298+39 – 12421+68 MVP-MN-276.03 ATWS 724	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☒ Trench Excavation
 ☒ Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☐ Other:

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-NN19.

STA 12376+00: Repair obstructed waterbar flow path.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: 07/30/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, July 30, 2019

Fig. 1: **STA 12308+00** – Perimeter controls in place and functioning. Topsoil piles stabilized with straw and millet.

148°SE (T) 37°15'15"N, 80°13'26"W ±16.4ft ▲ 2367ft



Fig. 2: **STA 12376+00** – Waterbar flow path obstructed. Maintain clear flowpath.

225°SW (T) 37°14'23"N, 80°13'5"W ±5541.6ft ▲ 1306ft



Fig. 3: **STA 12331+00** – Perimeter controls and slope drains in place and functioning. Topsoil piles stabilized with straw and millet.

109°E (T) 37°15'6"N, 80°11'22"W ±4639.3ft ▲ 1850ft



Fig. 4: **STA 12415+00** – Perimeter controls in place and functioning. Topsoil piles stabilized with straw and millet.

176°S (T) 37°14'14"N, 80°13'21"W ±5541.6ft ▲ 1381ft

