

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, July 24, 2019	Project Contact:	Brian Clauto
Spread H: Roanoke County	STA 12950+00 – 12973+43 MVP-RO-288	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Dormant

- | | Yes | No | N/A |
|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-Y7, S-Y8, W-Y2 and S-Y9.

Inspection of the MVP ROW between approximate STA 12950+00 and 12973+43. No ground disturbance has occurred in this area to date. Trees felled were flush cut and bridged over resources to prevent obstructed flow. DEQ Geologist Robert Howard met onsite for consultation. During the inspection it was determined that the current state of the ROW in this area, with no ground disturbance having occurred, was unlikely having significant impacts to quality or quantity of a ground water supply offsite.

Recommended Corrective Action: N/A

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 07/24/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, July 24, 2019

Fig. 1: **Stream S-Y8** – No ground disturbance. Trees flush cut and bridged over stream.



Fig. 2: **Stream S-Y7** – No ground disturbance. Trees flush cut and bridged over stream.



Fig. 3: **STA 12957+30** – No ground disturbance at MVP-RO-287 looking SW.



Fig. 4: **STA 12951+00** – No ground disturbance. Looking NW.

