

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, July 10, 2019	Project Contact:	Brian Clauto
Spread H: Franklin County	STA 13258+74 – 13262+66 MVP-FR-293.01 ATWS 1055	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Conventional Bore Site

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |


Comments: Inspected the following resources: S-II4 and W-II4.

Inspection of conventional bore site under stream S-II4 (STA 13260+75) at Flanders Road (MVP-FR-293.01).

Recommended Corrective Action: N/A

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: 07/10/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, July 10, 2019

Fig. 1: **Stream S-II4** – Clean bridge with sideboards in place and in good condition.



Fig. 2: **Stream S-II4** – GAS bore pit in progress. CFS and P1 in place and functioning properly. Perimeter berms adequately stabilized.



Fig. 3: **ATWS 1055** – Dewatering structure for GAS of conventional bore pit. Sediment bags are clean, filter structure intact and dewatering to stabilized area.



Fig. 4: **Stream S-II4** – Upstream view of stream S-II4 from construction bridge. Bridge sideboards in place and in good condition.

