

## FIELD INSPECTION

|                                                            |                                                    |                                |                 |
|------------------------------------------------------------|----------------------------------------------------|--------------------------------|-----------------|
| <b>Project Name:</b>                                       | Mountain Valley Pipeline                           | <b>Inspector:</b>              | Marshall Willis |
| <b>Inspection Date:</b>                                    | Wednesday, May 29, 2019                            | <b>Project Contact:</b>        | Brian Clauto    |
| <b>Spread I:</b><br>Franklin County<br>Pittsylvania County | STA 14548+75 – 14649+64<br>STA 15113+00 – 15142+72 | <b>Weather (Wet/Dry/Rain):</b> | Dry             |

**STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- |   |                                                                                                                                                                                 | Yes                                 | No                                  | N/A                      |
|---|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?                                                                                                                             | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-E18, S-E17, S-E14, S-H11 and S-A6.

STA 14568+10: Stabilize stream bank of S-E18.  
STA 15125+84: Repair P1.

**Recommended Corrective Action:** Maintain and install all controls per the approved plan and specs.

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 05/29/2019

## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, May 29, 2019

Fig. 1: **STA 14561+00** – Controls in place. Area stabilized with Earth Guard and straw.



Fig. 2: **STA 14508+10** – Stabilize bank of S-E18.



Fig. 3: **STA 14618+00** – Controls in place. Area establishing permanent vegetative cover.



Fig. 4: **STA 15125+84** – P1 maintenance needed.

