

FIELD INSPECTION

| Project Name: | Mountain Valley Pipeline | Inspector: | Marshall Willis |
|------------------------------|--|-------------------------|-----------------|
| Inspection Date: | Monday, May 20, 2019 | Project Contact: | Brian Clauto |
| Spread I: Franklin County | STA 13958+31 - 14010+00 STA 14011+00 - 14018+58 | Weather (Wet/Dry/Rain): | Dry |

| | | _ | | | |
|---|---------------------------------------|----------------|--|--|--|
| STAGE OF CONSTRUCTION: (Check all that apply) | | | | | |
| ☐ Clearing ☐ Rough Grading ☐ Trench Exca | Pipe Assembly, Testing & Installation | | | | |
| Backfilling and Grade Restoration Final Grading & Stabilization | | Other: Dormant | | | |
| | | | | | |
| | Yes No N/A | | | | |
| Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | | | | | |
| Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | | | | | |
| 3 Areas of offsite sediment deposition were observed? | | | | | |
| Comments: Inspected the following resources: S-KL38, W-EF48, S-KL35 and S-KL36. | | | | | |
| - STA 14008+75 – Remove fallen tree and repair ECDs. | | | | | |
| Recommended Corrective Action: Maintain and install all controls per the approved plan and specs. | | | | | |
| | | | | | |
| | | | | | |
| Deadline: Within 24-hr notification | | | | | |
| The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project | | | | | |

Date: 05/20/2019

Inspector Signature: _



FIELD INSPECTION PHOTO LOG

Project Name: <u>Mountain Valley Pipeline</u> Date: Monday, May 20, 2019

Fig. 1: **STA 13970+00** – Controls in place. Fig. 2: **STA 13980+00** – Controls in place. ₱ 122°SE (T) ● 37°0'47"N, 79°50'10"W ±7342.9ft ▲ 1133ft **②** 46°NE (T) **③** 37°2'57"N, 79°53'34"W ±16.4ft ▲ 1115ft Fig. 4: **STA 14015+55** – Controls in place. Fig. 3: **STA 14008+75** – Remove fallen tree. Repair ECDs.