

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, May 9, 2019	Project Contact:	Brian Clauto
Spread I: Pittsylvania County	STA 15498+70 – 15584+00	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|--------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☐ | ☒ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-CC11, S-CC10, S-CC9, S-CC15, S-MM8, S-CC13 and S-CC14.

- **STA 15562+25** – CFS in need of maintenance.
- **STA 15556+23** – P1 not properly entrenched.
- **STA 15551+50** – CFS undermined.
- **STA 15552+50** – IP/CFS maintenance needed.
- **STA 15514+00 - 15515+00** – CFS maintenance needed.
- **STA 15505+00** – Sump maintenance needed.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 05/09/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, May 9, 2019

Fig. 1: **STA 15584+00** – Controls in place.



Fig. 2: **STA 15572+71** – Controls in place. Area stabilized with Earth Guard and straw.



Fig. 3: **STA 15562+25** – CFS in need of maintenance.



Fig. 4: **STA 15556+23** – P1 not properly entrenched.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, May 9, 2019

Fig. 5: **STA 15551+50** – CFS undermined.



Fig. 6: **STA 15552+50** – IP/CFS maintenance needed.



Fig. 7: **STA 15514+00 - 15515+00** – CFS maintenance needed.



Fig. 8: **STA 15505+00** – Sump maintenance needed.

