

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, April 26, 2019	Project Contact:	Brian Clauto
Spread I: Franklin County	STA 13690+91 – 13713+56	Weather (Wet/Dry/Rain):	Rainy

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-E28, W-E7, W-E8, and S-E28.

STA 13712+50: CFS undermined in ATWS 1362.
 STA 13712+50: Maintain CFS, stabilize erosion in ATWS 1362.
 STA 13712+50: Maintain CFS, stabilize erosion in ATWS 1362.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 04/26/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, April 26, 2019

Fig. 1: **STA 13690+91** – Controls in place.



Fig. 2: **Wetland W-E7** – Controls in place.



Fig. 3: **Stream S-E28** – Controls in place.



Fig. 4: **STA 13707+00** – Area stabilized. Controls in place.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, April 26, 2019

Fig. 5: **STA 13712+50** – CFS undermined.



Fig. 6: **STA 13712+50** – CFS full, inadequate stabilization.



Fig. 7: **STA 13712+50** – CFS full, inadequate stabilization.



Fig. 8: **STA 13717+00** – Area stabilized. Controls in place.

