

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, April 22, 2019	Project Contact:	Brian Clauto
Spread I: Franklin County	STA 13626+10 – 13644+52	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Dormant

- | | Yes | No | N/A |
|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-E28.

STA 13642+19: CFS undermined on CIS of S-E28.

STA 13630+00 – STA 13631+50: Erosion on downslope side of permanent waterbar end treatments.

St. Clair Access Road: Stabilize shoulders of access road.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 04/22/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, April 22, 2019

Fig. 1: **STA 13642+19** – CFS undermined CIS S-E28.



Fig. 2: **STA 13630+00 – 13631+50** – Erosion below permanent waterbars.



Fig. 3: **STA 13630+00 – 13631+50** – Erosion below permanent waterbars.



Fig. 4: **St. Clair Access Road** – Stabilize shoulder of access road.

