

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, April 16, 2019	Project Contact:	Brian Clauto
Spread: Franklin County MP266 St#14063-14066 MP254 St#13415-13418	Spread I	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☒ | ☐ | ☐ |

Comments:

- Streams / wetlands inspected included: S-EF48, W-EF5
- Designated stream S-EF46 has been impacted with sediment, remove sediment
- St#13416+23 end treatment SSF is undermined and bare areas require stabilization
- St#13416+54 through 13418+00 check dams require maintenance and stabilization of conveyance channel
- St#13418+99 stockpiles require re stabilization
- St#13416+23 sediment is off of ROW, remove sediment

Recommended Corrective Action: Maintain all controls per the approved plan and specs, remove sediment per DEQ approval.

Deadline: Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 5-6-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, April 16, 2019

- Fig. 1 Designated stream S-EF46 has been impacted with sediment, remove sediment



- Fig. 2 St#13416+54 through 13418+00 check dams require maintenance and stabilization of conveyance channel



- Fig. 3 St#13416+23 sediment is off of ROW, remove sediment



- Fig. 4 St#13418+99 stockpiles require re stabilization



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, April 16, 2019

- Fig. 5 St#13416+23 end treatment SSF is undermined and bare areas require stabilization

