

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, April 12, 2019	Project Contact:	Brian Clauto
Spread I: Franklin County	STA 14524+76 – 14549+84 STA 14616+62 – 14649+47	Weather (Wet/Dry/Rain):	Rainy

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration
 ☒ Final Grading & Stabilization
 ☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|--------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☐ | ☒ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-G18.

STA 14532+00: Replace waddle.

STA 14533+00: Waterbar not per spec.

STA 14533+00: CWD does not have inlet protection. Inlet elevation too high.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 04/12/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, April 12, 2019

Fig. 1: **S-G18** – Controls in place.



Fig. 2: **STA 14532+00** – Repair/replace waddle.



Fig. 3: **STA 14533+00** – Waterbar not per spec.



Fig. 4: **STA 14533+00** – No inlet protection. Inlet too high.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, April 12, 2019

Fig. 5: **STA 14620+45** – Area at final stabilization.



Fig. 6: **STA 14630+48** – Area at final stabilization..



Fig. 7: **STA 14644+45** - Area at final stabilization.



Fig. 8: **STA 14647+87** – Area at final stabilization.

