

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, April 10, 2019	Project Contact:	Brian Clauto
Spread: Franklin County FR34 MP271 St#14354 MP263-265 St#13948-14000	Spread I	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☒ | ☐ | ☐ |

Comments:

- Streams / wetlands inspected included: SA-38, SA-40, W-CD1, S-CD1, SKL-35, W-EF48, SKL-36
- Designated stream SA-40 has been impacted this area was inspected and noted for corrective action on 4-9-19
- St#14354+10 hole in P1 fence
- St#14353+17 bank stabilization matting has fallen off slope
- St#14354+20 hole in sidewall protection of bridge
- St#13948+80 re-stabilization required before aquatic resource
- St#13990+31 re-stabilization required before aquatic resource

Recommended Corrective Action: Maintain all controls per the approved plan and specs, remove sediment per DEQ approval.

Deadline: Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 4/22/19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, April 10, 2019

- Fig. 1 Designated stream SA-40 has been impacted this area was inspected and noted for corrective action on 4-9-19.



- Fig. 2 St#14354+10 hole in P1 fence



- Fig. 3 St#14353+17 bank stabilization matting has fallen off slope



- Fig. 4 St#14354+20 hole in sidewall protection of bridge



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, April 10, 2019

- Fig. 5 St#13948+80 re-stabilization required before aquatic resource



- Fig. 6 St#13990+31 re-stabilization required before aquatic resource

