

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Friday, April 5, 2019	<b>Project Contact:</b>	Brian Clauto
<b>Spread I: Pittsylvania County</b>	H-603 STA 8+12 – STA 14+00 Transco Interconnect SWP H-602 STA 11+98 STA 16020+97 – STA 16006+05	<b>Weather (Wet/Dry/Rain):</b>	Rainy

**STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☒ Final Grading & Stabilization

☒ Other: Dormant

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-H44, S-EF26 and S-H44.

**Recommended Corrective Action:**

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 04/05/2019

## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, April 5, 2019

Fig. 1: **H-603 STA 8+12** – Area adequately stabilized with Earth Guard. Controls in place.



Fig. 2: **Transco Stormwater Pond** – Inlet channel K (CH-K).



Fig. 3: **Transco Stormwater Pond** – Inlet channel J (CH-J).



Fig. 4: **Transco Stormwater Pond** – Liner and baffle installation.



## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, April 3, 2019

Fig. 5: **STA 16020+97** – Area adequately stabilized with Earth Guard. Controls in place.



Fig. 6: **S-H44** – Area adequately stabilized. Controls in place.



Fig. 7: **S-EF26** – Area adequately stabilized. Controls in place.



Fig. 8: **H-602 STA 11+96** – Area adequately stabilized with Earth Guard. Controls in place.

