

## FIELD INSPECTION

|                              |                          |                         |                 |
|------------------------------|--------------------------|-------------------------|-----------------|
| Project Name:                | Mountain Valley Pipeline | Inspector:              | Marshall Willis |
| Inspection Date:             | Tuesday, April 2, 2019   | Project Contact:        | Brian Clauto    |
| Spread I:<br>Franklin County | STA 14546+85 – 14599+24  | Weather (Wet/Dry/Rain): | Dry             |

**STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation  
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Dormant

- |                                                                                                                                                                                   | Yes                      | No                                  | N/A                      |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|-------------------------------------|--------------------------|
| 1 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2 Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 Areas of offsite sediment deposition were observed?                                                                                                                             | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-E17 and S-E18.

STA 14583+56: Repair P1.  
STA 14549+84: No inlet protection on CWD.

**Recommended Corrective Action:** Maintain and install all controls per the approved plan and specs.

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 04/02/2019

## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, April 2, 2019

Fig. 1: **STA 14583+56** – ATWS 1043: Repair P1.



Fig. 2: **STA 14571+19** – Area adequately stabilized. Controls in place.



Fig. 3: **STA 14561+00** – Area adequately stabilized. Controls in place.



Fig. 4: **STA 14549+84** – CWD does not have inlet protection.

