

## FIELD INSPECTION

<b>Project Name:</b>	<b>Mountain Valley Pipeline</b>	<b>Inspector:</b>	<b>Marshall Willis</b>
<b>Inspection Date:</b>	<b>Thursday, March 21, 2019</b>	<b>Project Contact:</b>	<b>Brian Clauto</b>
<b>Spread I:</b> <b>Pittsylvania County</b>	<b>STA 15596+70 – 15619+48</b>	<b>Weather (Wet/Dry/Rain):</b>	<b>Rainy</b>

**STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation  
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Dormant

- |   | Yes                                 | No                                  | N/A                      |
|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-CC1, S-CC3 and S-P5.

- STA 15596+87 to STA 15600+12: Stabilize travel lane, no Earth Guard present.
- STA 15599+48: Repair CFS.
- STA 15600+50: Repair end treatment.
- STA 15603+50: Repair SSF.
- STA 15608+00: Adequately stabilize perimeter CWD.
- STA 15610+00: Repair P1.
- STA 15610+00: P1 Undermined, clean out CFS.
- STA 15611+66: Repair CFS.
- STA 15614+94: (S-P5) Repair CFS, remove sediment, stabilize banks.
- STA 15618+00: Adequately stabilize perimeter CWD.

**Recommended Corrective Action:** Maintain and install all controls per the approved plan and specs.

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 03/21/2019

# FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, March 21, 2019

Fig. 1: **STA 15596+87 to STA 15600+12** - Stabilize travel lane, no Earth Guard present.



Fig. 2: **STA 15599+48** - Repair CFS.



Fig. 3: **STA 15600+50** - Repair end treatment.



Fig. 4: **STA 15603+50** - Repair SSF.





# FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, March 21, 2019

Fig. 5: **STA 15608+00** - Adequately stabilize perimeter CWD.



Fig. 6: **STA 15610+00** - Repair P1.



Fig. 7: **STA 15610+00** - P1 Undermined, clean out CFS.



Fig. 8: **STA 15611+66** - Repair CFS.





## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, March 21, 2019

Fig. 9: **STA 15614+94** - (S-P5) Repair CFS, remove sediment, stabilize banks.



Fig. 10: **STA 15618+00** - Adequately stabilize perimeter CWD.

