

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, February 22, 2019	Project Contact:	Brian Clauto
Spread I: Franklin County Pittsylvania County	STA 14981+55 – 14950+47 STA 14981+55 – 15028+09	Weather (Wet/Dry/Rain):	Rainy

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☒ Trench Excavation
 ☒ Pipe Assembly, Testing & Installation
☒ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☐ Other:

- | | | Yes | No | N/A |
|---|---|--------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☐ | ☒ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments:

- Streams / wetlands inspected included: S-G13, W-MM17, S-D7, S-D3 and S-D4.
- Undermined CFS at STA 14968+00.
- CFS needs maintenance at STA 14953+00.
- CFS needs maintenance at STA 14975+00.
- Erosion fabric needs maintenance at STA 14975+00.
- Inadequate stabilization around MLV 33 at STA 14979+85.
- CFS needs maintenance at STA 14983+20.
- CFS needs maintenance at STA 14983+20.
- CFS needs maintenance at STA 14986+00.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 02/22/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, February 22, 2019

Fig. 1: STA 14968+00 – Undermined CFS.



Fig. 2: STA 14953+00 – CFS full.



Fig. 3: STA 14975+00 – CFS full.



Fig. 4: STA 14975+00 – Erosion fabric maintenance.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, February 22, 2019

Fig. 5: **STA 14979+85** – Inadequate stabilization.



Fig. 6: **STA 114983+20**– CFS full.




Fig. 7: **STA 14983+20** – CFS maintenance needed.



Fig. 8: **STA 14986+00**– CFS maintenance needed.

