

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, February 21, 2019	Project Contact:	Brian Clauto
Spread H: Franklin County	STA 13315+32 – 13273+02 STA 13344+00 – 13403+28	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☒ Trench Excavation
 ☒ Pipe Assembly, Testing & Installation
☒ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☐ Other:

- | | | Yes | No | N/A |
|---|---|--------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☐ | ☒ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments:

- Streams / wetlands inspected included: S-GH7, S-RR8, S-RR9 and S-RR11.
- CWD does not have inlet protection at STA 13345+70.
- CWD does not have inlet protection at CIS S-RR8.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: 02/21/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, February 21, 2019

Fig. 1: **CIS S-GH7** – Controls in place.




Fig. 2: **STA 13288+04** – Area stabilized.



Fig. 3: **STA 13344+25** – Area stabilized.



Fig. 4: **STA 13345+70** – Inlet protection needed.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, February 21, 2019

Fig. 5: **CIS S-RR8** – Inlet protection needed.



Fig. 6: **STA 13355+68** – Area stabilized.



Fig. 7: **STA 13357+85** – S-R11 controls in place. Area stabilized.



Fig. 8: **STA 13387+00** – Area stabilized.

