

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, January 22, 2019	Project Contact:	Brian Clauto
Spread: Montgomery County MP234-235	Spread H	Weather (Wet/Dry/Rain):	Dry
STAGE OF CONSTRUCTION: (Check all that apply)			
Clearing	Rough Grading	Trench Excavation	Pipe Assembly, Testing & Installation
Backfilling and Grade	e Restoration	& Stabilization	Other: dormant
		Yes No N/A	
	d and implemented in accordance with the nt control plan and stormwater manageme		
	ures properly maintained in effective oper nce with good engineering practices and, turer specifications?		
3 Areas of offsite sedi	ment deposition were observed?		
Comments:			
■ MP 234 St#12381+00 CFS and P1 silt fence is torn.			
Recommended Corrective Action : Maintain all controls per the approved plan and annual standards and specs.			
Deadline: _Within 24hr notification			
The recommended corrective constitute non-compliance and ensuring compliance on the above the control of the co	action deadline date applies to all conditions no d/or corrective actions are not completed by the pove project.	oted on this report unless otherwis e deadline, other enforcement action	e noted. If listed condition(s) currently ons may be issued to the entity responsible for

Inspector Signature:___



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Tuesday, January 22, 2019

Fig. 1 MP 234 St#12381+00 CFS and P1 silt fence is torn.



Fig. 2 St#12374+56 no activity at designated stream crossing S-0016.



Fig. 3 At St#12420+44 matting has been installed



■ Fig. 4.