

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, March 1, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12298+39 – 12371+23 MVP-MN-276.03	Weather:	Rainy

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A.

**Routine Maintenance:** (72-Hour Deadline from Notification)

- STA 12338+50: Trash/construction debris deposited into controls.
- STA 12352+00: Trash/construction debris blowing off ROW.
- STA 12361+00: SSF maintenance required.

**Recommended Corrective Action:** Maintain and install all controls per the approved PSS&S. Provide good "housekeeping" measures to prevent trash and debris from impacting ESC controls or blowing off ROW.

**Deadline:** Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** **Monday, March 1, 2021**

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Monday, March 1, 2021

**Figure 1: STA 12330+00** – Controls in place and functioning properly. Area stabilized with erosion control matting.

**BRG:** 121°SE (T) **LAT:** 37.254191 **LON:** -80.210126 ±4101ft **ALT:** 2654ft



**Figure 2: STA 12361+00** – SSF maintenance required.

**BRG:** 30°NE (T) **LAT:** 37.239924 **LON:** -80.212973 ±22399ft **ALT:** 1529ft



**Figure 3: STA 12338+50** – Trash and construction debris deposited in controls.

**BRG:** 230°SW (T) **LAT:** 37.252720 **LON:** -80.214043 ±32ft **ALT:** 1601ft



**Figure 4: STA 12352+00** – Construction debris deposited off ROW.

**BRG:** 102°E (T) **LAT:** 37.250782 **LON:** -80.210317 ±16ft **ALT:** 1532ft

