

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, March 24, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 12994+02 – 13063+00 MVP-FR-290	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-G24, W-ST2-PEM, S-H1, S-G26, S-G27, S-G25, W-KL41, S-RR16, W-RR3, S-RR18 and W-RR4.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, March 24, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, March 24, 2021

Figure 1: STA 12996+00 – Controls in place and functioning properly.
BRG: 106°E (T) LAT: 37.130701 LON: -80.130706 ±541ft ALT: 2640ft



Figure 2: STA 13017+00 – Controls in place and functioning properly.
BRG: 101°E (T) LAT: 37.125474 LON: -80.122712 ±164ft ALT: 3019ft



Figure 3: STA 13041+00 – Controls in place and functioning properly.
BRG: 133°SE (T) LAT: 37.115051 LON: -80.077529 ±16421ft ALT: 2763ft



Figure 4: STA 13060+00 – Controls in place and functioning properly.
BRG: 119°SE (T) LAT: 37.125336 LON: -80.112661 ±24158ft ALT: 2712ft

