

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, March 19, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14845+68 – 14928+52	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-H17, W-H6, S-A7, S-SS8, S-CD8, S-AB8, S-DD3 and S-G16.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Friday, March 19, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, March 19, 2021

Figure 1: STA 14852+00 – Controls in place and functioning properly. Area stabilized with straw and Earth-Guard.

BRG: 111°E (T) LAT: 36.972147 LON: -79.663285 ±16ft ALT: 928ft



Figure 2: STA 14865+00 – Controls in place and functioning properly. Area stabilized with straw and Earth-Guard.

BRG: 117°SE (T) LAT: 37.009545 LON: -79.734079 ±16421ft ALT: 919ft



Figure 3: STA 14880+00 – Controls in place and functioning properly. Area stabilized with straw and Earth-Guard.

BRG: 117°SE (T) LAT: 36.970552 LON: -79.654287 ±32ft ALT: 937ft



Figure 4: STA 14899+00 – Controls in place and functioning properly. Area stabilized with straw and Earth-Guard.

BRG: 109°E (T) LAT: 36.969439 LON: -79.648331 ±32ft ALT: 739ft

