

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, March 17, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12071+80 – 12190+95 MVP-MN-270 MVP-MN-274	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-MM15, S-MM14, S-MM13, S-MM11, S-F15, W-F9-PFO, S-F16A/B, W-C12, S-C36, W-C11, S-MM31, S-C29, S-C5 and S-C24.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, March 17, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, March 17, 2021

Figure 1: STA 12073+00 – Controls in place and functioning properly. Area stabilized with erosion control matting and straw.
BRG: 357°N (T) LAT: 37.230819 LON: -80.260627 ±7205ft ALT: 1297ft



Figure 2: STA 12138+00 – Controls in place and functioning properly. Area stabilized with erosion control matting and straw.
BRG: 102°E (T) LAT: 37.256126 LON: -80.276270 ±16ft ALT: 1420ft



Figure 3: STA 12162+00 – Controls in place and functioning properly. Area stabilized with erosion control matting and straw.
BRG: 98°E (T) LAT: 37.250842 LON: -80.267059 ±3051ft ALT: 1447ft



Figure 4: STA 12172+00 – Controls in place and functioning properly. Area stabilized with erosion control matting and straw.
BRG: 99°E (T) LAT: 37.231655 LON: -80.260382 ±7205ft ALT: 1420ft

